

Supplier: 50999

Ship To: 201

Revision: 0

**HILING PRODUCTION CO.**  
1385 SENGSHUNG BUSINESS PARK  
HILING 234567  
HILING  
China

**ACME, INC.**  
(WAREHOUSE ENTRANCE)  
1-531 STH. MAIN STREET  
EUROBONGA NY 34005  
USA

Confirmed: **yes**  
Order Date: 18 Jun 2011  
Print Date: 18 Jun 2011  
Buyer: **WPG**  
FOB: **LAX CA**  
Ship Via: **FEDEX COLLECT**

Supplier: **QUING PANG**  
Supplier Phone: **+86 512 8888 9999**

PLEASE INCLUDE DROP TEST CARD IN PACKAGE

PLEASE ENSURE GOODS ARE FREE FROM DIRT AND DUST (UNLIKE THE PRIOR SHIPMENT). THIS IS OUR SECOND ORDER AND IF THIS IS OF GOOD QUALITY WE WILL SHIFT OUR FUTURE ORDERS TO HILING PRODUCTION CO.

Item	Product	Product Name & Details	Due Date	Quantity UoM	Unit Price	Extended Cost
1	51A12-191 KICKPLATE KG20 2347 Site: 200 Rev'n: C Manufacturer: HILING THIS ITEM SHOULD BE CHECKED FOR ROUGH EDGES ON THE SPLINE PLATE AT THE REAR BEFORE PACKING AS SOME EARLY MODELS FAILED WHEN CONNECTED.	Supplier Code: 331-465 20 Manuf. Code: 331-465 20 2011	18-Jun-2011	10.0 EA	351.00	3,510.00
2	51A12-193 UPPER FRONT PANEL KG20 2347 Rev'n: B Manufacturer: HILING		18-Jun-2011	20.0 EA	450.00	9,000.00
3	51A12-502 KICKPLATE KM20 2500		18-Jun-2011	30.0 EA	250.00	7,500.00
4	51A14-128 KICKPLATE KG20 3900 DOUBLE WRAPPING REQUIRED ON THESE ITEMS TO PREVENT DUST CONTAMINATION WHILE BEING TRANSPORTED TO DUST-HAZARD LOCATION.		18-Jun-2011	40.0 EA	22.00	880.00
5	51A12-191 KICKPLATE KG20 2347 Site: 200 Rev'n: C Manufacturer: HILING THIS ITEM SHOULD BE CHECKED FOR ROUGH EDGES ON THE SPLINE PLATE AT THE REAR BEFORE PACKING AS SOME EARLY MODELS FAILED WHEN CONNECTED.	Supplier Code: 331-465 20 Manuf. Code: 331-465 20 2011	18-Jun-2011	10.0 EA	351.00	3,510.00
6	51A12-193 UPPER FRONT PANEL KG20 2347 Rev'n: B Manufacturer: HILING		18-Jun-2011	20.0 EA	450.00	9,000.00
7	51A12-502 KICKPLATE KM20 2500		18-Jun-2011	30.0 EA	250.00	7,500.00
8	51A12-191 KICKPLATE KG20 2347 Site: 200 Rev'n: C Manufacturer: HILING THIS ITEM SHOULD BE CHECKED FOR ROUGH EDGES ON THE SPLINE PLATE AT THE REAR BEFORE PACKING AS SOME EARLY MODELS FAILED WHEN CONNECTED.	Supplier Code: 331-465 20 Manuf. Code: 331-465 20 2011	18-Jun-2011	10.0 EA	351.00	3,510.00
9	51A12-193 UPPER FRONT PANEL KG20 2347 Rev'n: B Manufacturer: HILING		18-Jun-2011	20.0 EA	450.00	9,000.00

Supplier: 50999

Ship To: 201

Revision: 0

**HILING PRODUCTION CO.**

**ACME, INC.**

Confirmed: **yes**

Order Date: **18 Jun 2011**

Item	Product	Product Name & Details	Due Date	Quantity UoM	Unit Price	Extended Cost
			B/Fwd from Page 1			<b>53,410.00</b>
10	51A12-502 KICKPLATE KM20 2500 Site: 200		18-Jun-2011	30.0 EA	250.00	7,500.00
11	51A12-191 KICKPLATE KG20 2347 Site: 200 Rev'n: C Manufacturer: HILING	Supplier Code: 331-465 20 Manuf. Code: 331-465 20 2011 THIS ITEM SHOULD BE CHECKED FOR ROUGH EDGES ON THE SPLINE PLATE AT THE REAR BEFORE PACKING AS SOME EARLY MODELS FAILED WHEN CONNECTED.	18-Jun-2011	10.0 EA	351.00	3,510.00
12	51A12-502 KICKPLATE KM20 2500		18-Jun-2011	30.0 EA	250.00	7,500.00
13	51A12-194 Kickplate, 250mm, 20Kg load. This panel has in-built external front facing power outlets. This version has 4 US power outlets at BOTH left and right for a total of 8 outlet positions. Covers that hide the power outlets when not in use are included. Site: 200 Rev'n: C Manufacturer: HILING	Supplier Code: 331-465 20 Manuf. Code: 331-465 20 2011 PLEASE UNBOX AND WRAP EACH ITEM AS A MAIL PARCEL AS THESE ARE SINGLE ORDERS WHICH WE WILL SHIP IN YOUR PACKAGING TO THE END BUYER.	18-Jun-2011	10.0 EA	351.00	3,510.00
<b>Lines Total:</b> <b>G.S.T.:</b> <b>Invoice Total:</b>						<b>67,930.00</b> <b>0.00</b> <b>67,930.00</b>

**Terms: 30 DAYS FROM INVOICE**